

Star Motors
 Facility #: 7081784
 1694 Union Center Highway
 Endicott, NY 13760-1341
 607-786-3918 Fax: 607-697-0511
 E-mail: starmotors@stny.rr.com
 Web Site: www.300sel.com

Date In:	10/29/2024
Date Out:	
Service Order #:	21235
Page:	1

Customer:
Dubey, Neil 1694 Union Center Highway Endicott, NY 13760

Manufacturer: Mercedes-Benz
Model: 280sel
Serial Number: 10801912003415
Alternate ID:
Reference: 280sel
Mileage: 3670

Phone: 754-0192	Alternate Phone:	Terms: net 30				
Service Rep: NEIL	Cust PO:	Status: OPEN				
Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended

Job:1 Technician: robin

CUSTOMER STATES: master cylinder leaks into booster clutch sticks
WORK PERFORMED: replace brake booster replace master cylinder replace slave cylinder replace clutch cylinder has new clutch and pressure plate installed in 2k miles ago 2018

LABOR				
		6.00	145.00	870.00
000-295-78-06	Clutch master cylinder for W108.018	1.00	142.00	142.00
000-430-55-30	Brake booster for W108,W112, W113 ATE # 03.6197-0220.4 slip on brake booster vacuum line. Early T51. replaced by 002-430-68-30	1.00	950.00	950.00
001-295-68-07	Pedal assembly slave cylinder for W115	1.00	170.00	170.00
002-430-28-01	ATE master cylinder for W109 ATE# 03.2123-1003.3	1.00	290.00	290.00
BRAKE FLUID	ATE brake fluid, 1 liter super blue, bf 1sb, DOT 4	1.00	23.50	23.50

<u>PARTS TOTALS FOR THIS JOB:</u>	\$1,575.50
<u>TOTAL LABOR FOR THIS JOB</u>	\$870.00
<u>TOTAL PARTS AND LABOR</u>	\$2,445.50

Parts:	1,575.50	Labor:	870.00	Sublet:	0.00	Disposal:	0.00	Pickup/Delivery:	0.00
								Service Call:	0.00
						Tax:	0.00	Total:	2,445.50
								Prepaid:	0.00
								Paid:	0.00

Balance: 2,445.50

I hereby authorize the above repairs _____