Facility #: 7081784 1694 Union Center Highway Endicott, NY 13760-1341 607-786-3918 Fax: 607-697-0511

E-mail: starmotors@stny.rr.com
Web Site: www.300sel.com

Date In: Date Out:	6/20/2023
Service Order #:	19668
Page:	1

Customer:	
Dubey, Neil	
1694 Union Center Highway	
Endicott, NY 13760	

Manufacturer: Mercedes-Benz

Model: 300SEL

Serial Number: 10901812002981

Phone: 754-0192	Alternate Phone) :	Terr	ns: net 30	
Service Rep: JAKE	Cust PO	: Status: OPEN	Due Da	ate: 6/20/2023	
Job #Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended
Job:1 Technician:					
		CUSTOMER STATES:check over f	or resale		
		WORK PERFORMED:			
	PARTS TOT	ALS FOR THIS JOB:			\$0.00
		OR FOR THIS JOB			\$0.00 \$0.00
		TS AND LABOR			\$0.00
Job:2 Technician: neil					70.00
		CUSTOMER STATES:install front a	and rear shocks		
		WORK PERFORMED:			
	LABOR		4.00	135.00	540.00
109-320-00-30	Bilstein front s	shock absorber for W109. Bilstein car 244-005074 oe number	2.00	244.00	488.00
109-320-00-31		osorber for W109. Bilstein #B 46	2.00	240.00	480.00
103 020 00 01	534. 2x car	Solber for W 100. Blistelli #B 40	2.00	240.00	400.00
	PARTS TOT	ALS FOR THIS JOB:			\$968.0
		OR FOR THIS JOB			\$540.0
	TOTAL PAR	TS AND LABOR			\$1,508
Job:3 Technician: robin					
		CUSTOMER STATES:install new g	as tank and pur	тр	
		WORK PERFORMED:			
	LABOR		6.00	135.00	810.00
001-091-52-01		d and brown terminal posts, short 0 or W109. Bosch # 0442201001 2 do not sell	1.00	895.00	895.00
109-470-05-01		k for W109.018. 8mm steel	1.00	1,890.00	1,890.00
	return, 11mm	steel outlet, 5 mm vent lines steel		•	,
111-470-06-86		re 8mm x10mm od for W100 all early cars	1.00	20.60	20.60
111-410-00		·	1.00	20.00	∠0.00
		ALS FOR THIS JOB:			\$2,805
		<u>OR FOR THIS JOB</u> TS AND LABOR			\$810.0 \$3,615

Facility #: 7081784 1694 Union Center Highway Endicott, NY 13760-1341 607-786-3918 Fax: 607-697-0511

E-mail: starmotors@stny.rr.com

Web Site: www.300sel.com

Customer: Dubey, Neil 1694 Union Center Highway Endicott, NY 13760

Date In: 6/20/2023 Date Out: Service Order #: 19668 Page:

Manufacturer: Mercedes-Benz

Model: 300SEL

Serial Number: 10901812002981

Phone: 754-0192 A	Iternate Phone):	Term	s: net 30	
ervice Rep: JAKE	Cust PO: Status: OPE		Due Date: 6/20/2023		
ob #Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended
lob:4 Technician:robin					
		CUSTOMER STATES:install front be	ellows		
		WORK PERFORMED:			
	LABOR		6.00	135.00	810.00
112-320-36-15	Left front air b and tested for	ag chamber w/air bag assembled W109	1.00	650.00	650.00
112-320-37-15		bag chamber w/air bag d tested for W109	1.00	650.00	650.00
	PARTS TOT	ALS FOR THIS JOB:			\$1,300.0
		OR FOR THIS JOB			\$810.00
	TOTAL PAR	TS AND LABOR			\$2,110.0
Job:5 Technician:robin					
		CUSTOMER STATES:broken manif	old studs right s	ide.	
		WORK PERFORMED: remove head injection pum	l, replace gaske pp and clean. vis		move
	LABOR		45.00	135.00	6,075.00
100-010-10-21	Right cylinder W109	head gasket set for W100 &	1.00	950.00	950.00
	TOTAL LAB	ALS FOR THIS JOB: OR FOR THIS JOB TS AND LABOR			\$950.00 \$6,075.0 \$7,025.0

Facility #: 7081784 1694 Union Center Highway Endicott, NY 13760-1341 607-786-3918 Fax: 607-697-0511

E-mail: starmotors@stny.rr.com
Web Site: www.300sel.com

Date In: 6/20/2023
Date Out:

Service Order #: 19668
Page: 3

Customer:

Dubey, Neil
1694 Union Center Highway
Endicott, NY 13760

Manufacturer: Mercedes-Benz

Model: 300SEL

Serial Number: 10901812002981

Phone: 754-0192	Alternate Phone	:	Term	s: net 30	
Service Rep: JAKE	Cust PO:	Status: OPEN	N Due Dat	e: 6/20/2023	
Job #Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended
Job:6 Technician:rob	in				
		CUSTOMER STATES:remove bat recharge sy		st, remove a/c l	ines and
			ds, new battery, n se clear 040 black ew copper seals,	. remove air cl	eaner, all
	LABOR		40.00	135.00	5,400.00
100-540-00-31-14	W100,108,109	negative 2 gauge, 14" long for 9,111,112, 113 114 115 116 s2bk- 14in-38 negative	1.00	40.00	40.00
111-987-03-40		e between hood and fender for 9.018, 2x car triangle	2.00	3.00	6.00
201-988-02-11	hood stop buff	er for W201. 2x/car	2.00	1.70	3.40
Job:7 Technician: neil	TOTAL LABO	ALS FOR THIS JOB: OR FOR THIS JOB TS AND LABOR			\$49.40 \$5,400.0 \$5,449.4
		CUSTOMER STATES:install new	air filters, install v	vipers	
		WORK PERFORMED: customer p	av		
	LABOR		2.00	135.00	270.00
000-824-06-27	Wiper blade in	nsert for W100 & W109, 400mm	2.00	45.00	90.00
108-830-01-18	Right cowl fres	sh air filter screen for W109	1.00	27.00	27.00
108-830-02-18	left cowl fresh from 000247	air filter screen for W109.018,	1.00	27.00	27.00
	TOTAL LAB	ALS FOR THIS JOB: OR FOR THIS JOB TS AND LABOR			\$144.00 \$270.00 \$414.00

Facility #: 7081784 1694 Union Center Highway Endicott, NY 13760-1341 607-786-3918 Fax: 607-697-0511

E-mail: starmotors@stny.rr.com Web Site: www.300sel.com

Date In: Date Out:	6/20/2023
Service Order #:	19668
Page:	4

6/20/2023

Customer: Dubey, Neil 1694 Union Center Highway Endicott, NY 13760

Manufacturer: Mercedes-Benz

Model: 300SEL

Serial Number: 10901812002981

Phone : 754-0192 A Service Rep : JAKE	Iternate Phone Cust PO			ns: net 30 ate: 6/20/2023	
Job #Stock Code		Indications/Work Performed	Quantity	Price	Extended
ob:8 Technician:robin	-			·	
		CUSTOMER STATES:install exhasu	ıt.		
		WORK PERFORMED:			
	LABOR		20.00	135.00	2,700.00
300SEL 6.3 EXHAUST	steel pipes pa	Osel 6.3 exhaust system complete, sinted black, hangers, rubber bump e tips, seals, bolts	1.00	3,000.00	3,000.00
	TOTAL LAB	TALS FOR THIS JOB: BOR FOR THIS JOB RTS AND LABOR			\$3,000.0 \$2,700.0 \$5,700.0
lob:9 Technician:					
		CUSTOMER STATES:install motor	mounts.		
		WORK PERFORMED: customer pay	/.		
109-586-00-22	Front motor m	nount kit for W109.018	1.00	850.00	850.00
	TOTAL LAB	TALS FOR THIS JOB: BOR FOR THIS JOB RTS AND LABOR			\$850.00 \$0.00 \$850.00
Job:10 Technician:robin		CUSTOMER STATES:steering gear	box loose. no	leaks	
		WORK PERFORMED: rebuild box a sheet	nd add couple	r. align car to sp	ec. see data
	LABOR		8.00	135.00	1,080.00
109-460-04-02	Power steeringbox	g gearbox, rebuilt, for W109.018	1.00	950.00	950.00
115-460-05-10	• •	oling for W108.018, from 058444	1.00	127.00	127.00
ATF	Dexron Type	3 automatic transmission fluid	1.00	5.00	5.00
	TOTAL LAB	TALS FOR THIS JOB: BOR FOR THIS JOB RTS AND LABOR			\$1,082.0 \$1,080.0 \$2,162.0

Facility #: 7081784 1694 Union Center Highway Endicott, NY 13760-1341 607-786-3918 Fax: 607-697-0511

E-mail: starmotors@stny.rr.com
Web Site: www.300sel.com

Date In: 6/20/2023
Date Out:

Service Order #: 19668
Page: 5

\$2,958.50

Customer:
Dubey, Neil
1694 Union Center Highway
Endicott, NY 13760

Manufacturer: Mercedes-Benz

Model: 300SEL

Serial Number: 10901812002981

Alternate ID: BLACK Reference: black 6.3 Mileage: 89988

	Alternate Phone:			s : net 30	
Service Rep: JAKE	Cust PO:	Status: OPEN	Due Dat	e: 6/20/2023	
Job #Stock Code	Description I	ndications/Work Performed	Quantity	Price	Extended
Job:11 Technician: ADM	IIN _				
		CUSTOMER STATES:rebuild distril	butor.		
		WORK PERFORMED: change to pe	ertronix custome	r pav	
	LABOR	, , , , , , , , , , , , , , , , , , ,	6.00	135.00	810.00
001-158-01-01		acuum advance unit. Bosch # or W100.981 or W109 pertronix	1.00	950.00	950.00
	TOTAL LABO	LS FOR THIS JOB: R FOR THIS JOB S AND LABOR			\$950.00 \$810.00 \$1,760.0
Job:12 Technician:robir)				
		CUSTOMER STATES: calipers froz	en		
		WORK PERFORMED: replace all 4 leak on peda years old.	brake calipers. bal depression. ma		
	LABOR		8.00	135.00	1,080.00
000-423-93-98	Left rear caliper to 003548 See	for W109.018 only, rebuilt, up Notes.	1.00	350.00	350.00
000-423-94-98		er for W109.018 only, vented, 3548. See Notes.	1.00	350.00	350.00
000-428-58-35	Rear brake hose both ends. 2x/ca	e for W109.018, 350mm, female ar	1.00	85.00	85.00
002-421-54-98	Vented left front	t caliper for W109. See Notes.	1.00	480.00	480.00
002-421-55-98	Vented right from	nt caliper for W109. See notes.	1.00	480.00	480.00
667-428-01-35	Front brake hos cohline stock	e for W109.018 420mmlong use	2.00	55.00	110.00
BRAKE FLUID	ATE brake fluid 4	, 1 liter super blue, bf 1sb, DOT	1.00	23.50	23.50
	PARTS TOTA				

TOTAL PARTS AND LABOR

Facility #: 7081784 1694 Union Center Highway Endicott, NY 13760-1341 607-786-3918 Fax: 607-697-0511

E-mail: starmotors@stny.rr.com
Web Site: www.300sel.com

Date In: 6/20/2023
Date Out:

Service Order #: 19668
Page: 6

\$231.50

Customer:
Dubey, Neil
1694 Union Center Highway
Endicott, NY 13760

Manufacturer: Mercedes-Benz

Model: 300SEL

Serial Number: 10901812002981

Alternate ID: BLACK Reference: black 6.3 Mileage: 89988

Phone: 754-0192	Alternate Phone	e:	Term	s: net 30	
Service Rep: JAKE	Cust PO:	Status: OPE	N Due Dat	te: 6/20/2023	
Job #Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended
Job:13 Technician:nei	I				
		CUSTOMER STATES:windsheild	washer in operati	ve	
		WORK PERFORMED: adjust nozz	zles for sprayer. n e for wind shield v		er hose, new
	LABOR		3.00	135.00	405.00
.*.	WASHER FL	UID	1.00	4.00	4.00
002-997-59-82		r windshield washer hose for 9 4mm ID x 6mm OD hose not	3.00	11.00	33.00
108-869-00-20	Windshield wa	asher bottle for W109	1.00	174.00	174.00
115-869-01-69	•	Plastic top for windshield washer reservoir for W109.018. SEE NOTES.		35.00	35.00
Job:14 Technician:rob	TOTAL LAB	ALS FOR THIS JOB: OR FOR THIS JOB TS AND LABOR			\$246.00 \$405.00 \$651.00
		CUSTOMER STATES:oil change			
		WORK PERFORMED: filter an 11	quarts of oil		
	LABOR		1.00	135.00	135.00
000-180-04-09		100.981 or W109.018 engine, D. See notes	1.00	25.50	25.50
10W-40	10w-40 engine	e oil	11.00	5.00	55.00
ZDDP	zddp oil addat	ive zinc dialkyl dithiophosphate	2.00	8.00	16.00
		ALS FOR THIS JOB: OR FOR THIS JOB			\$96.50 \$135.0

TOTAL PARTS AND LABOR

Facility #: 7081784 1694 Union Center Highway Endicott, NY 13760-1341 607-786-3918 Fax: 607-697-0511

E-mail: starmotors@stny.rr.com
Web Site: www.300sel.com

Date In: Date Out:	6/20/2023
Service Order #:	19668
Page:	7

Customer:
Dubey, Neil
1694 Union Center Highway Endicott, NY 13760
Endicott, NT 13700

Manufacturer: Mercedes-Benz

Model: 300SEL

Serial Number: 10901812002981

Alternate ID: BLACK Reference: black 6.3 Mileage: 89988

Phone: 754-0192	Alternate Phone	:	Terr	ns: net 30	
Service Rep: JAKE	Cust PO:	Status: OPEN	Due Da	ate: 6/20/2023	
Job #Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended
Job:15 Technician:eri	С				
		CUSTOMER STATES:radiator and v	water pump lea	ak.	
		WORK PERFORMED: replace water	r pump and rad	ditor	
	LABOR		6.00	135.00	810.00
100-200-16-20		ebuilt, for W100.981 or ee notes. Fits 300sel	1.00	650.00	650.00
> 100-201-13-80	6 hole water po W100.981 or V	ump gasket for V109.018	1.00		
> 100-203-00-80		m top of water ostat housing for V109.0018	1.00		
109-501-06-01	Radiator for W	109.018. Behr #110151	1.00	1,100.00	1,100.00
Q-1-03-0002	Mercedes Ben Bitrix.	z factory yellow antifreeze w/	1.00	24.00	24.00
	TOTAL LAB	ALS FOR THIS JOB: OR FOR THIS JOB TS AND LABOR			\$1,774.00 \$810.00 \$2,584.00

Parts:	16,094.00	Labor:	20,925.00	Sublet:	0.00	Disposal:	0.00	Pickup/Delivery:	0.00
								Service Call:	0.00
						Tax:	0.00	Total:	37,019.00
								Prepaid:	0.00
								Paid:	0.00
								Deleneer	27.040.00
								Balance:	37,019.00

I hereby authorize the above repairs _____