

**Star Motors**  
 Facility #: 7081784  
 1694 Union Center Highway  
 Endicott, NY 13760-1341  
 607-786-3918 Fax: 607-697-0511  
 E-mail: starmotors@stny.rr.com  
 Web Site: www.300sel.com

Date In:	5/31/2022
Date Out:	
Service Order #:	18436
Page:	1

Customer:  
 Schwan, Steven  
 8200 E Belleview  
 Greenwood Village, CO 80011

Manufacturer: Mercedes Benz  
 Model: 280SEL 4.5  
 Serial Number: 10806812009426  
 Alternate ID: 1972 WHITE  
 Reference: white 280sel  
 Mileage: 35382

<b>Phone:</b> 303-995-2253	<b>Alternate Phone:</b>	<b>Terms:</b>				
<b>Service Rep:</b> JAKE	<b>Cust PO:</b>	<b>Status:</b> OPEN				
		<b>Due Date:</b> 5/31/2022				
<b>Job #</b>	<b>Stock Code</b>	<b>Description</b>	<b>Indications/Work Performed</b>	<b>Quantity</b>	<b>Price</b>	<b>Extended</b>

Job:1 Technician:robin

**CUSTOMER STATES:**check timing chain and perform compression check

**WORK PERFORMED:** replace chain and tensioner  
 compression excellent 150psi

<u>LABOR</u>		12.00	135.00	1,620.00
000-997-75-94	Timing chain for W116.981. 186 links. SEE NOTES.	1.00	200.00	200.00
116-050-16-11	Chain tensioner for W116.981	1.00	230.00	230.00

**PARTS TOTALS FOR THIS JOB:** **\$430.00**  
**TOTAL LABOR FOR THIS JOB** **\$1,620.00**  
**TOTAL PARTS AND LABOR** **\$2,050.00**

Job:2 Technician:neil

**CUSTOMER STATES:**paint sides of car, remove scratches

**WORK PERFORMED:** install trunk pad, remove trunk and clean. respray trunk in original black as needed. replace flat spare tire, install jack and tool kit as needed.

paint side of car in original 158 Grey beige paint. hood roof are in original Grey Beige DB158 paint. buff out still excellent. blocks side of chip and repaint in ppg base clear.

rockers are all solid. rear quarters are excellent, floor boards excellent. rear spare tire trunk wells excellent. prior work in front rocker splash area and lower fenders. still excellent was left alone. bumper core support solid rust free. car was ziebarted from new.

check rear valance no body work, never hit in rear .body gaps are all at 4 mm. check pinch welds all excellent. wheel arches are excellent.

<u>LABOR</u>		25.00	135.00	3,375.00
108-684-01-05A	Rubber trunk floor mat for W108, W109, W111 aftermarket	1.00	300.00	300.00
110-610-00-52	Front jack hole mount for w109.018, 2x car	2.00	33.00	66.00
110-610-04-52	Rear jack hole mount for W109. 2x car	2.00	50.00	100.00

**PARTS TOTALS FOR THIS JOB:** **\$466.00**  
**TOTAL LABOR FOR THIS JOB** **\$3,375.00**  
**TOTAL PARTS AND LABOR** **\$3,841.00**

**Star Motors**  
 Facility #: 7081784  
 1694 Union Center Highway  
 Endicott, NY 13760-1341  
 607-786-3918 Fax: 607-697-0511  
 E-mail: starmotors@stny.rr.com  
 Web Site: www.300sel.com

Date In:	5/31/2022
Date Out:	
Service Order #:	18436
Page:	2

<b>Customer:</b> Schwan, Steven 8200 E Belleview Greenwood Village, CO 80011
---

Manufacturer: Mercedes Benz Model: 280SEL 4.5 Serial Number: 10806812009426 Alternate ID: 1972 WHITE Reference: white 280sel Mileage: 35382
--

**Phone:** 303-995-2253    **Alternate Phone:**    **Terms:**

**Service Rep:** JAKE    **Cust PO:**    **Status:** OPEN    **Due Date:** 5/31/2022

Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended
-------	------------	-------------	----------------------------	----------	-------	----------

Job:3    Technician: robin

<b>CUSTOMER STATES:</b> install rear shocks, front shocks replaced by owner
<b>WORK PERFORMED:</b> front shocks ok, rears replaced

Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended
		<b>LABOR</b>		2.00	135.00	270.00
108-320-01-31		Rear shock absorber for W108 & W111. Bilstein # B46-0537 kyb installed		2.00	145.00	290.00

**PARTS TOTALS FOR THIS JOB:**    **\$290.00**  
**TOTAL LABOR FOR THIS JOB**    **\$270.00**  
**TOTAL PARTS AND LABOR**    **\$560.00**

Job:4    Technician: neil

<b>CUSTOMER STATES:</b> install new tires
<b>WORK PERFORMED:</b>

205/70/14		205/70/14 Yokohama Avid T4 performance tire kuhmos installed		4.00	91.00	364.00
TIRE MOUNT		Mount tire & rim to car.		4.00	15.00	60.00

**PARTS TOTALS FOR THIS JOB:**    **\$424.00**  
**TOTAL LABOR FOR THIS JOB**    **\$0.00**  
**TOTAL PARTS AND LABOR**    **\$424.00**

Job:5    Technician: robin

<b>CUSTOMER STATES:</b> charge a/c
<b>WORK PERFORMED:</b> removed condenser and replaced. ice cold air.

Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended
		<b>LABOR</b>		6.00	135.00	810.00
000-835-66-98		#8 copper crush washer for a/c santech		2.00	3.00	6.00
108-835-07-70		rebuilt late style condenser 109.057 chassis only		1.00	1,800.00	1,800.00

**PARTS TOTALS FOR THIS JOB:**    **\$1,806.00**  
**TOTAL LABOR FOR THIS JOB**    **\$810.00**  
**TOTAL PARTS AND LABOR**    **\$2,616.00**

**Star Motors**  
 Facility #: 7081784  
 1694 Union Center Highway  
 Endicott, NY 13760-1341  
 607-786-3918 Fax: 607-697-0511  
 E-mail: starmotors@stny.rr.com  
 Web Site: www.300sel.com

Date In:	5/31/2022
Date Out:	
Service Order #:	18436
Page:	3

Customer:  
 Schwan, Steven  
 8200 E Belleview  
 Greenwood Village, CO 80011

Manufacturer: Mercedes Benz  
 Model: 280SEL 4.5  
 Serial Number: 10806812009426  
 Alternate ID: 1972 WHITE  
 Reference: white 280sel  
 Mileage: 35382

<b>Phone:</b> 303-995-2253	<b>Alternate Phone:</b>	<b>Terms:</b>				
<b>Service Rep:</b> JAKE	<b>Cust PO:</b>	<b>Status:</b> OPEN				
		<b>Due Date:</b> 5/31/2022				
<b>Job #</b>	<b>Stock Code</b>	<b>Description</b>	<b>Indications/Work Performed</b>	<b>Quantity</b>	<b>Price</b>	<b>Extended</b>

Job:6 Technician:robin

**CUSTOMER STATES:**windsheild washer not functioning  
**WORK PERFORMED:** replaces hoses and top cap.

	<b>LABOR</b>	2.00	135.00	270.00
000-869-18-47	Windshield washer nozzle for W109	1.00	67.00	67.00

**PARTS TOTALS FOR THIS JOB:** \$67.00  
**TOTAL LABOR FOR THIS JOB** \$270.00  
**TOTAL PARTS AND LABOR** \$337.00

Job:7 Technician:robin

**CUSTOMER STATES:**battery weak  
**WORK PERFORMED:** install battery and battery cables

	<b>LABOR</b>	2.00	135.00	270.00
000-982-33-08	Mercedes Benz classic battery lead acid group	1.00	350.00	350.00
	49 large battery			
108-540-07-30 36	Positive cable for 3.5 and 4.5 36 inches long 2 gage number 10 mm connector for starter battery cable s2bk-36in-pos-36	1.00	100.00	100.00
201-540-00-31	Negative cable 2 guage, 8mm end, 12 inches long. W108, W109, W110, W111, W113, W100 battery cable.	1.00	30.00	30.00

**PARTS TOTALS FOR THIS JOB:** \$480.00  
**TOTAL LABOR FOR THIS JOB** \$270.00  
**TOTAL PARTS AND LABOR** \$750.00

Job:8 Technician:robin

**CUSTOMER STATES:**change oil  
**WORK PERFORMED:**

	<b>LABOR</b>	1.00	135.00	135.00
000-180-06-09	oil filter kit for W116 & W117, Hengst E121HD01	1.00	10.00	10.00
10W-40	10w-40 engine oil	10.00	8.00	80.00
ZDDP	zddp oil addative zinc dialkyl dithiophosphate	1.00	8.00	8.00

**PARTS TOTALS FOR THIS JOB:** \$98.00  
**TOTAL LABOR FOR THIS JOB** \$135.00  
**TOTAL PARTS AND LABOR** \$233.00

**Star Motors**  
 Facility #: 7081784  
 1694 Union Center Highway  
 Endicott, NY 13760-1341  
 607-786-3918 Fax: 607-697-0511  
 E-mail: starmotors@stny.rr.com  
 Web Site: www.300sel.com

Date In:	5/31/2022
Date Out:	
Service Order #:	18436
Page:	4

Customer:  
 Schwan, Steven  
 8200 E Belleview  
 Greenwood Village, CO 80011

Manufacturer: Mercedes Benz  
 Model: 280SEL 4.5  
 Serial Number: 10806812009426  
 Alternate ID: 1972 WHITE  
 Reference: white 280sel  
 Mileage: 35382

<b>Phone:</b> 303-995-2253	<b>Alternate Phone:</b>	<b>Terms:</b>				
<b>Service Rep:</b> JAKE	<b>Cust PO:</b>	<b>Status:</b> OPEN				
		<b>Due Date:</b> 5/31/2022				
<b>Job #</b>	<b>Stock Code</b>	<b>Description</b>	<b>Indications/Work Performed</b>	<b>Quantity</b>	<b>Price</b>	<b>Extended</b>

Job:9 Technician:neil

**CUSTOMER STATES:**exhaust donuts are weak

**WORK PERFORMED:** chane exhaust donuts

<b>LABOR</b>	1.00	135.00	135.00
107-492-00-82 Rubber dampening donut on rear muffler for W109. 4x car 111	4.00	1.70	6.80

**PARTS TOTALS FOR THIS JOB: \$6.80**  
**TOTAL LABOR FOR THIS JOB \$135.00**  
**TOTAL PARTS AND LABOR \$141.80**

Job:10 Technician:robin

**CUSTOMER STATES:**remove antenna original hirschman and repair.

**WORK PERFORMED:** radio function is excellent. antenna replaced with hirschmann mechanical

<b>LABOR</b>	2.00	135.00	270.00
000-827-44-01 000-827-44-01 original manual antenna hirschmann, non electric, with key 023 961-000 DS Hit Auta 2630 A HIT marked on antenna	1.00	180.00	180.00

**PARTS TOTALS FOR THIS JOB: \$180.00**  
**TOTAL LABOR FOR THIS JOB \$270.00**  
**TOTAL PARTS AND LABOR \$450.00**

Job:11 Technician:robin

**CUSTOMER STATES:**safety check

**WORK PERFORMED:** check all light and brake functions.

check interior dimmer light  
 check all brake lights, turn signal etc. make sure vehicle passed ny state inspection.  
 calipers, brakes pads and rotors replaced by customer.

Job:12 Technician:robin

**CUSTOMER STATES:**road test car. 1800 miles with out a fault.

**WORK PERFORMED:**

<b>LABOR</b>	2.00	135.00	270.00
--------------	------	--------	--------

**PARTS TOTALS FOR THIS JOB: \$0.00**  
**TOTAL LABOR FOR THIS JOB \$270.00**  
**TOTAL PARTS AND LABOR \$270.00**

**Star Motors**  
 Facility #: 7081784  
 1694 Union Center Highway  
 Endicott, NY 13760-1341  
 607-786-3918 Fax: 607-697-0511  
 E-mail: starmotors@stny.rr.com  
 Web Site: www.300sel.com

Date In:	5/31/2022
Date Out:	
Service Order #:	18436
Page:	5

<b>Customer:</b> Schwan, Steven 8200 E Belleview Greenwood Village, CO 80011
---

Manufacturer: Mercedes Benz Model: 280SEL 4.5 Serial Number: 10806812009426 Alternate ID: 1972 WHITE Reference: white 280sel Mileage: 35382
--

<b>Phone:</b> 303-995-2253	<b>Alternate Phone:</b>	<b>Terms:</b>				
<b>Service Rep:</b> JAKE	<b>Cust PO:</b>	<b>Status:</b> OPEN				
		<b>Due Date:</b> 5/31/2022				
<b>Job #</b>	<b>Stock Code</b>	<b>Description</b>	<b>Indications/Work Performed</b>	<b>Quantity</b>	<b>Price</b>	<b>Extended</b>

Job:13 Technician:ROBIN

<b>CUSTOMER STATES:</b> brake flush
<b>WORK PERFORMED:</b> replace all 4 brake hoses.

Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended
		<b>LABOR</b>		3.00	135.00	405.00
000-428-26-35		Right rear brake hose for W108. 265 mm long double female connector		1.00	79.00	79.00
000-428-26-35		Right rear brake hose for W108. 265 mm long double female connector		1.00	79.00	79.00
123-428-05-35		Front wheel brake hose for W100		2.00	22.00	44.00
	BRAKE FLUID	ATE brake fluid, 1 liter super blue, bf 1sb, DOT 4		1.00	23.50	23.50

<b>PARTS TOTALS FOR THIS JOB:</b>	<b>\$225.50</b>
<b>TOTAL LABOR FOR THIS JOB</b>	<b>\$405.00</b>
<b>TOTAL PARTS AND LABOR</b>	<b>\$630.50</b>

Job:14 Technician:neil

<b>CUSTOMER STATES:</b> compression test 10232023
<b>WORK PERFORMED:</b> 1=150, 2=150, 3=145, 4=160,5=150, 6=150 7=150 8=150 compression ratio 8 to 1. compression good, spark plugs clean

<b>LABOR</b>	2.00	135.00	270.00
<b>PARTS TOTALS FOR THIS JOB:</b>			<b>\$0.00</b>
<b>TOTAL LABOR FOR THIS JOB</b>			<b>\$270.00</b>
<b>TOTAL PARTS AND LABOR</b>			<b>\$270.00</b>

Job:15 Technician:neil

<b>CUSTOMER STATES:</b> red levers bind on heater core.
<b>WORK PERFORMED:</b> remove ashtray. Clean radiator with citric acid and flush. flush 10 times and refill with coolant. heater valves work fine, blower works fine. water temperature is 175 constant.

<b>LABOR</b>	4.00	135.00	540.00
G001-100	Blue coolant for Mercedes Benz	1.00	29.43
<b>PARTS TOTALS FOR THIS JOB:</b>			<b>\$29.43</b>
<b>TOTAL LABOR FOR THIS JOB</b>			<b>\$540.00</b>
<b>TOTAL PARTS AND LABOR</b>			<b>\$569.43</b>

**Star Motors**  
 Facility #: 7081784  
 1694 Union Center Highway  
 Endicott, NY 13760-1341  
 607-786-3918 Fax: 607-697-0511  
 E-mail: starmotors@stny.rr.com  
 Web Site: www.300sel.com

Date In:	5/31/2022
Date Out:	
Service Order #:	18436
Page:	6

<b>Customer:</b> Schwan, Steven 8200 E Belleview Greenwood Village, CO 80011
---

Manufacturer: Mercedes Benz Model: 280SEL 4.5 Serial Number: 10806812009426 Alternate ID: 1972 WHITE Reference: white 280sel Mileage: 35382
--

<b>Phone:</b> 303-995-2253	<b>Alternate Phone:</b>	<b>Terms:</b>				
<b>Service Rep:</b> JAKE	<b>Cust PO:</b>	<b>Status:</b> OPEN				
		<b>Due Date:</b> 5/31/2022				
<b>Job #</b>	<b>Stock Code</b>	<b>Description</b>	<b>Indications/Work Performed</b>	<b>Quantity</b>	<b>Price</b>	<b>Extended</b>

Job:16 Technician:NEIL

<b>CUSTOMER STATES:</b> rear fuel hoses and filter have been changed by previous customer.
<b>WORK PERFORMED:</b>

<b><u>PARTS TOTALS FOR THIS JOB:</u></b>	<b>\$0.00</b>
<b><u>TOTAL LABOR FOR THIS JOB</u></b>	<b>\$0.00</b>
<b><u>TOTAL PARTS AND LABOR</u></b>	<b>\$0.00</b>

Job:17 Technician:matt

<b>CUSTOMER STATES:</b> central locking check valve broke.
<b>WORK PERFORMED:</b> replace valve

<b><u>LABOR</u></b>		0.20	135.00	27.00
116-800-03-78	Central locking check valve in engine bay for W109.018 blue	1.00	21.00	21.00

<b><u>PARTS TOTALS FOR THIS JOB:</u></b>	<b>\$21.00</b>
<b><u>TOTAL LABOR FOR THIS JOB</u></b>	<b>\$27.00</b>
<b><u>TOTAL PARTS AND LABOR</u></b>	<b>\$48.00</b>

Parts:	4,523.73	Labor:	8,667.00	Sublet:	0.00	Disposal:	0.00	Pickup/Delivery:	0.00
								Service Call:	0.00
						Tax:	1,055.26	Total:	14,245.99
								Prepaid:	0.00
								Paid:	0.00

**Balance:** 14,245.99

I hereby authorize the above repairs \_\_\_\_\_