

Star Motors
 Facility #: 7081784
 1694 Union Center Highway
 Endicott, NY 13760-1341
 607-786-3918 Fax: 607-697-0511
 E-mail: starmotors@stny.rr.com
 Web Site: www.300sel.com

Date In:	8/5/2024
Date Out:	8/29/2024
Service Order #:	20951
Page:	1

Customer:
 Ofer, JJ
 312 wood duck road
 Amenia, NY 12051

Manufacturer: Mercedes-Benz
 Model: 280sel
 Serial Number: 10801912003415
 Alternate ID:
 Reference: 1969 280sel
 Mileage: 03630 km

Phone: 9176085753	Alternate Phone:	Terms: credit card				
Service Rep: NEIL	Cust PO:	Status: CLOSED Due Date: 8/5/2024				
Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended

Job:1 Technician:neil

CUSTOMER STATES:general check up of car:
WORK PERFORMED: will need shocks, brake hoses, brakes, oil change master cylinder, check all fluids, recommned 123 ignition as well to update.

PARTS TOTALS FOR THIS JOB: \$0.00
TOTAL LABOR FOR THIS JOB \$0.00
TOTAL PARTS AND LABOR \$0.00

Job:2 Technician:robin

CUSTOMER STATES:replace shocks and front end parts as needed. align car.
WORK PERFORMED: replace all 4 shocks with original bilstein.

	<u>LABOR</u>			
		6.00	145.00	870.00
107-330-01-03	Front axle tie rod w/left & right ends for W109	2.00	85.00	170.00
108-320-00-30	Front shock absorber for W111	2.00	278.00	556.00
108-320-01-31	Rear shock absorber for W108 & W111. Bilstein # B46-0537	2.00	145.00	290.00
110-460-02-05	Center drag link for W109 w111 w113 w108	1.00	204.00	204.00
111-330-03-30	Lateral cross strut support from unit body to subframe for W108	1.00	165.00	165.00

PARTS TOTALS FOR THIS JOB: \$1,385.00
TOTAL LABOR FOR THIS JOB \$870.00
TOTAL PARTS AND LABOR \$2,255.00

Star Motors
 Facility #: 7081784
 1694 Union Center Highway
 Endicott, NY 13760-1341
 607-786-3918 Fax: 607-697-0511
 E-mail: starmotors@stny.rr.com
 Web Site: www.300sel.com

Date In:	8/5/2024
Date Out:	8/29/2024
Service Order #:	20951
Page:	2

Customer: Ofer, JJ 312 wood duck road Amenia, NY 12051

Manufacturer: Mercedes-Benz Model: 280sel Serial Number: 10801912003415 Alternate ID: Reference: 1969 280sel Mileage: 03630 km

Phone: 9176085753	Alternate Phone:	Terms: credit card				
Service Rep: NEIL	Cust PO:	Status: CLOSED				
		Due Date: 8/5/2024				
Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended

Job:3 Technician: robin

CUSTOMER STATES: repair brakes

WORK PERFORMED: rebuild brake system

Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended
		LABOR		14.00	145.00	2,030.00
000-420-46-83		Left rear caliper, non-vented, new for W108, w112, w113		1.00	468.00	468.00
000-420-47-83		Right rear caliper, non-vented, new for W108 W112 and W113. obsolete. new exchange.		1.00	468.00	468.00
000-428-26-35		Right rear brake hose for W108. 265 mm long double female connector		1.00	79.00	79.00
000-428-79-35		Left rear brake hose for w108, up to 034763		1.00	35.00	35.00
001-420-77-20		Front brake pad set for W109.		1.00	57.00	57.00
001-420-79-20		Rear brake pad set for W109 from 005869, PDR #D102D		1.00	63.00	63.00
001-421-81-98		Front left caliper, non-vented, less lining, for W109.015 new		1.00	480.00	480.00
001-421-82-98		Right front caliper, non-vented, for W109.015 w109, w108 w113		1.00	480.00	480.00
002-430-28-01		ATE master cylinder for W109 ATE# 03.2123-1003.3		1.00	348.00	348.00
003-997-93-46		front wheel seal 45x62 10/12mm for W109		2.00	12.50	25.00
115-421-11-12		Front brake rotor for W108.018, up to 075175, used on W111, W112, W109 early, W108 early, solid rotor		2.00	300.00	600.00
123-428-05-35		Front wheel brake hose for W100		2.00	22.00	44.00
126-423-00-12		ATE rear brake rotor for W126, w108, w111, w109, zimmerman		2.00	64.00	128.00
BRAKE FLUID		ATE brake fluid, 1 liter super blue, bf 1sb, DOT 4		1.00	23.50	23.50

PARTS TOTALS FOR THIS JOB:

\$3,298.50

TOTAL LABOR FOR THIS JOB

\$2,030.00

TOTAL PARTS AND LABOR

\$5,328.50

Star Motors
 Facility #: 7081784
 1694 Union Center Highway
 Endicott, NY 13760-1341
 607-786-3918 Fax: 607-697-0511
 E-mail: starmotors@stny.rr.com
 Web Site: www.300sel.com

Date In:	8/5/2024
Date Out:	8/29/2024
Service Order #:	20951
Page:	3

Customer: Ofer, JJ 312 wood duck road Amenia, NY 12051

Manufacturer: Mercedes-Benz Model: 280sel Serial Number: 10801912003415 Alternate ID: Reference: 1969 280sel Mileage: 03630 km

Phone: 9176085753	Alternate Phone:	Terms: credit card				
Service Rep: NEIL	Cust PO:	Status: CLOSED Due Date: 8/5/2024				
Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended

Job:4 Technician:robin

CUSTOMER STATES:tune car up

WORK PERFORMED: replace plugs, convert distributor to electronic,air filter spark plugs and wires, set co on car. change oil, fuel filter and oil. set valve lash on engine and CO car. re check timing chain, replace differential fluid, check transmission fluid. check radiator anti freeze. car set to 3.5 percent co at idle.

Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended
		LABOR		20.00	145.00	2,900.00
000-094-58-04		Air filter for W100.981 or W109.018, subbed		1.00	47.00	47.00
		617-094-00-04				
000-180-06-09		oil filter kit for W116 & W117, Hengst		1.00	10.00	10.00
		E121HD01				
000-477-64-15		Fuel filter for W100 & W109.018. Mann # P707.		1.00	11.00	11.00
		See Notes.				
002-158-38-01		M130 Bosch distributor rebuilt cast iron housing		1.00	1,650.00	1,650.00
100-997-00-40		Square cut seal ring for fuel filter on W109.018		1.00	1.50	1.50
		or W100. See notes.				
	10W-40	10w-40 engine oil		8.00	5.00	40.00
	ZDDP	zddp oil addative zinc dialkyl dithiophosphate		1.00	8.00	8.00

PARTS TOTALS FOR THIS JOB: **\$1,767.50**
TOTAL LABOR FOR THIS JOB **\$2,900.00**
TOTAL PARTS AND LABOR **\$4,667.50**

Job:5 Technician:robin

CUSTOMER STATES:fuel pump leaks

WORK PERFORMED: replace pump

Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended
		LABOR		3.00	145.00	435.00
001-091-52-01		Fuel pump, red and brown terminal posts, short		1.00	995.00	995.00
		body for W100 or W109. Bosch # 0442201001				
		or 0442201002. do not sell				

PARTS TOTALS FOR THIS JOB: **\$995.00**
TOTAL LABOR FOR THIS JOB **\$435.00**
TOTAL PARTS AND LABOR **\$1,430.00**

Star Motors
 Facility #: 7081784
 1694 Union Center Highway
 Endicott, NY 13760-1341
 607-786-3918 Fax: 607-697-0511
 E-mail: starmotors@stny.rr.com
 Web Site: www.300sel.com

Date In:	8/5/2024
Date Out:	8/29/2024
Service Order #:	20951
Page:	4

Customer: Ofer, JJ 312 wood duck road Amenia, NY 12051

Manufacturer: Mercedes-Benz Model: 280sel Serial Number: 10801912003415 Alternate ID: Reference: 1969 280sel Mileage: 03630 km

Phone: 9176085753	Alternate Phone:	Terms: credit card				
Service Rep: NEIL	Cust PO:	Status: CLOSED Due Date: 8/5/2024				
Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended

Job:6 Technician:robin

CUSTOMER STATES:change tires dry rotted

WORK PERFORMED: change tires to 215/70/14 black wall

215/70/14	Cooper Trendsetter tire, 215/70/14.	4.00	150.00	600.00
TIRE DISPOSAL	NY tire disposal fee	4.00	3.50	14.00
TIRE MOUNT & BALAN	Tire mount and balance.	4.00	30.00	120.00
TIRE TAX	NY new tire tax	4.00	2.50	10.00

PARTS TOTALS FOR THIS JOB: **\$744.00**
TOTAL LABOR FOR THIS JOB **\$0.00**
TOTAL PARTS AND LABOR **\$744.00**

Job:7 Technician:robin

CUSTOMER STATES:a/c weak

WORK PERFORMED: charge a/c

	<u>LABOR</u>	1.00	145.00	145.00
A/C 134A	A/C system recharge with R134a	1.00	230.00	230.00

PARTS TOTALS FOR THIS JOB: **\$230.00**
TOTAL LABOR FOR THIS JOB **\$145.00**
TOTAL PARTS AND LABOR **\$375.00**

Job:8 Technician:robin

CUSTOMER STATES:***added to estimate**** shifter bushing missing

WORK PERFORMED:

	<u>LABOR</u>	0.50	145.00	72.50
210-992-00-10	shifter bushing w210, cite vin when ordering.	1.00	3.00	3.00

PARTS TOTALS FOR THIS JOB: **\$3.00**
TOTAL LABOR FOR THIS JOB **\$72.50**
TOTAL PARTS AND LABOR **\$75.50**

Job:9 Technician:robin

CUSTOMER STATES:during test a/c stopped working.

WORK PERFORMED: recharge a/c corroded contacts on fuse box

	<u>LABOR</u>	2.00	145.00	290.00
--	---------------------	------	--------	--------

PARTS TOTALS FOR THIS JOB: **\$0.00**
TOTAL LABOR FOR THIS JOB **\$290.00**
TOTAL PARTS AND LABOR **\$290.00**

Star Motors
 Facility #: 7081784
 1694 Union Center Highway
 Endicott, NY 13760-1341
 607-786-3918 Fax: 607-697-0511
 E-mail: starmotors@stny.rr.com
 Web Site: www.300sel.com

Date In:	8/5/2024
Date Out:	8/29/2024
Service Order #:	20951
Page:	5

Customer:
 Ofer, JJ
 312 wood duck road
 Amenia, NY 12051

Manufacturer: Mercedes-Benz
 Model: 280sel
 Serial Number: 10801912003415
 Alternate ID:
 Reference: 1969 280sel
 Mileage: 03630 km

Phone: 9176085753	Alternate Phone:	Terms: credit card				
Service Rep: NEIL	Cust PO:	Status: CLOSED Due Date: 8/5/2024				
Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended

Job:10 Technician:robin

CUSTOMER STATES:rear brake line are incorrectly made with buble flares
WORK PERFORMED: remake rear brake lines out of copper. remake brake lines from bauble flare to double flare.

LABOR	6.00	145.00	870.00
*. copper line	1.00	60.00	60.00
<u>PARTS TOTALS FOR THIS JOB:</u>			\$60.00
<u>TOTAL LABOR FOR THIS JOB</u>			\$870.00
<u>TOTAL PARTS AND LABOR</u>			\$930.00

Job:11 Technician:robin

CUSTOMER STATES:rear reverse light do not work
WORK PERFORMED: clean contact on transmission reverse switch

LABOR	1.00	145.00	145.00
--------------	------	--------	--------

Job:12 Technician:robin

CUSTOMER STATES:items that it will eventually need and observations.
WORK PERFORMED: 3 gear synchro is notch leave alone.
 replace drive shaft (done)

 the observation do not detract from driving the car, these are recommendation to the car for long term care

 car has been converted from a 012 automatic car to a manual. the car has been repainted from 904 dark blue to olive green. the car has prior lower body rust repair that has been properly done. overall solid car.

 heater works fine but right red lever is stuck, leave alone.

<u>PARTS TOTALS FOR THIS JOB:</u>	\$0.00
<u>TOTAL LABOR FOR THIS JOB</u>	\$0.00
<u>TOTAL PARTS AND LABOR</u>	\$0.00

Star Motors
 Facility #: 7081784
 1694 Union Center Highway
 Endicott, NY 13760-1341
 607-786-3918 Fax: 607-697-0511
 E-mail: starmotors@stny.rr.com
 Web Site: www.300sel.com

Date In:	8/5/2024
Date Out:	8/29/2024
Service Order #:	20951
Page:	6

Customer:
 Ofer, JJ
 312 wood duck road
 Amenia, NY 12051

Manufacturer: Mercedes-Benz
 Model: 280sel
 Serial Number: 10801912003415
 Alternate ID:
 Reference: 1969 280sel
 Mileage: 03630 km

Phone: 9176085753	Alternate Phone:	Terms: credit card				
Service Rep: NEIL	Cust PO:	Status: CLOSED Due Date: 8/5/2024				
Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended

Job:13 Technician:robbin

CUSTOMER STATES:after driving car at higher speeds a driveline vibration emanates

WORK PERFORMED: flex disc worn out, you joint is worn out, center support worn, drive shaft out of balance replace, ll these item by using a 6.3 drive shaft. Vibration eliminated.

	LABOR		8.00	145.00	1,160.00
109-410-09-03	Two part propeller shaft for W109.018. rebuilt drive shaft		1.00	2,000.00	2,000.00
126-410-02-15	Flexible joint disc		1.00	112.00	112.00

PARTS TOTALS FOR THIS JOB: **\$2,112.00**
TOTAL LABOR FOR THIS JOB **\$1,160.00**
TOTAL PARTS AND LABOR **\$3,272.00**

Job:14 Technician:robin

CUSTOMER STATES:car hits a wall and stumbles at 4100 rpm

WORK PERFORMED: check fuel pressure, excellent at 14 psi at cold start, check gas tank, excellent, check fuel hose, repositioned hose, problem went away.

LABOR		2.00	145.00	290.00
--------------	--	------	--------	--------

PARTS TOTALS FOR THIS JOB: **\$0.00**
TOTAL LABOR FOR THIS JOB **\$290.00**
TOTAL PARTS AND LABOR **\$290.00**

Job:15 Technician:neil

CUSTOMER STATES:change battery and add gas to car 93 octane.

WORK PERFORMED:

	LABOR		1.00	145.00	145.00
001-982-80-08	agm battery for all mercedes		1.00	258.00	258.00

PARTS TOTALS FOR THIS JOB: **\$258.00**
TOTAL LABOR FOR THIS JOB **\$145.00**
TOTAL PARTS AND LABOR **\$403.00**

Star Motors
 Facility #: 7081784
 1694 Union Center Highway
 Endicott, NY 13760-1341
 607-786-3918 Fax: 607-697-0511
 E-mail: starmotors@stny.rr.com
 Web Site: www.300sel.com

Date In:	8/5/2024
Date Out:	8/29/2024
Service Order #:	20951
Page:	7

Customer:
 Ofer, JJ
 312 wood duck road
 Amenia, NY 12051

Manufacturer: Mercedes-Benz
 Model: 280sel
 Serial Number: 10801912003415
 Alternate ID:
 Reference: 1969 280sel
 Mileage: 03630 km

Phone: 9176085753	Alternate Phone:	Terms: credit card				
Service Rep: NEIL	Cust PO:	Status: CLOSED Due Date: 8/5/2024				
Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended

Job: 16 Technician: greg

CUSTOMER STATES: Perform New York State inspection
WORK PERFORMED: safety only

PARTS TOTALS FOR THIS JOB: \$0.00
TOTAL LABOR FOR THIS JOB \$0.00
TOTAL PARTS AND LABOR \$0.00

Parts:	10,853.00	Labor:	9,352.50	Sublet:	10.00	Disposal:	0.00	Pickup/Delivery:	0.00	
								Service Call:	0.00	
						Tax:	1,616.44	Total:	21,831.94	
								Prepaid:	0.00	
								Paid:	21,831.94	
									Balance:	0.00

I hereby authorize the above repairs _____